## Risk Assessment for Gunnersbury Triangle Sports and Social Club, Jan 2024



Updated and reviewed by Robert Underwood: Health and Safety and Building and Maintenance Officer January 2024

**Overall responsibility for Health and Safety: Management Committee:** 

H/S- Health and Safety.

B/M-Building and Maintenance.

M/C-Management Committee.

## Part 1: Statement of Intent;

- Ensure accidents are prevented by managing health and safety risks.
- Provide clear instruction and information and adequate training to club members.
- Engage and consult with club members on a day-day basis on all H/S issues.
- Implement emergency procedures evacuation in case of fire or other significate incidence.
- Maintain a safe and healthy club environment and provide and maintain the building, plant and sports equipment.
- Publicize that health and safety is the responsibility of all individual members.

## Risk Assessment over view for Gunnersbury Triangle Sports and Social Club, January 2024

Main recommendations and review	Responsibility of	Do by / completed date
<ul> <li>1. Fire Safety (Medium Risk)</li> <li>a) Continue checking Fire Action notices and Fire Evacuation Routes are displayed and that Fire Exits are marked and have notices to be kept clear. Risk to fire access in Tudor Room due to excessive storage and storage of flammable materials karate and aikido mats.</li> <li>b) Mark floor area to be kept clear (hazard tape and signage)</li> <li>c) Remind Bar staff to check fire exits are clear when they check premises.</li> <li>d) Provide Fire training for bar staff</li> <li>e) Review Fire Risk Assessment.</li> <li>f) Renew fire safety certificate.</li> <li>g) Karate and aikido mats have no fire safety certificate</li> </ul>	a) H/S b) and c) B/M H/S. d)e)f) H/S	1a)More storage required in Tudor Room exit to avoid blocking fire access. Fire risk form karate and aikido mats 1d)Fire training of bar staff completed Aug 2023 1f)Completed April 2023 1g) Advisory. Store karate and aikido mats in another area. Reduce the amount.
<ul> <li>2. Tripping hazards: (Medium Risk)</li> <li>a) Upgrade pathway to court 6 risk tractor might turn over</li> <li>b) Continued vigilance to ensure potential hazards (obstacles, equipment, broken furniture etc.), in and around clubhouse are removed, and paths are kept clear.</li> </ul>	a) B/M b) All club members.	2a) Completed Aug 2023 2b) Ongoing
3. Contractors: (low risk)  Check that contractors are properly insured. (Condition of insurance.) Applies to contractors using potentially dangerous equipment or working on electrical or gas installation, roof etc. Does not apply to, for example, a worker doing painting or a minor repair. Procedure required (low risk)	H/S Officer and B/M	3)Ongoing
4. Review First Aid Provision: (High Risk) also see section 13 below  A. Make list of first aiders on notice board. B. Provide on line first aid training for new volunteers and refresher training where required. C. Publicise the use of The Club's defibrillator in newsletter by Utube video. D. Provide annual club training event for fire safety and using the defibrillator. E. Provide introduction for new members, to include H/S, safeguarding issues, history of the club. All accidents must be must be recorded in the log book (High Risk f) Check first aid supplies up to date  5. Club Security: (High Risk) Repair front entrance and side entrance gate. Raise height of entrance fence to 2m.  6. Tennis Court Safety: (High Risk) Review tennis court maintenance procedure.  7. PAT and gas certification. (High Risk)  8. Renew insurances policies. (High Risk)	H/S, B/M , M/C B/M B/M M/C	4d) Training provided for bar staff and club members in defibrillator and fire safety Sept 2023. 4f)First aid box replaced Jan 2024 5) Fence needs to be reviewed 6) Ongoing Philippa Wallbank 7) Current till Nov 2024 8) Current till Aug 2024

Who might be harmed and how?		Further actions required	Action by		Date
			whom	when	completed
ds (Medium /low Ri	sk.)				
<ul> <li>Uneven flooring</li> <li>Wet flooring</li> <li>Spillages</li> <li>Trailing wires</li> <li>Obstructions and obstacles</li> <li>Sand on courts</li> <li>Uneven, overgrown or slippery paths</li> <li>Ramps and steps</li> <li>Dirty floor in Tudor Room causing slipping when used by table tennis</li> <li>Anyone using the club might trip and sustain an injury</li> <li>B/M inspects premises regularly &amp; carries out repairs</li> <li>There is a Maintenance Reporting book for recording accidents. (located in the Kitchen)</li> <li>There is an Accident Reporting book for recording accidents. (located in the kitchen)</li> <li>A professional firm cleans the club. It has a schedule of work and reports to the B/M to identify problems</li> <li>Floors are usually washed out-of-hours and are not wet when the club is in use. Wet floor sign available.</li> <li>Adequate lighting throughout clubhouse and surrounds</li> <li>Raised sills on the two doors to the exterior in the lounge are marked with hazard tape</li> <li>Storage areas are provided and regularly reviewed</li> <li>The is a Maintenance Reporting book for recording accidents. (located in the Kitchen)</li> <li>A professional firm cleans the club. It has a schedule of work and reports to the B/M to identify problems</li> <li>Floors are usually washed out-of-hours and are not wet when the club is in use. Wet floor sign available.</li> <li>Adequate lighting throughout clubhouse and surrounds</li> <li>Raised sills on the two doors to the exterior in the lounge are marked with hazard tape</li> <li>Storage areas are provided and regularly reviewed</li> <li>The allotment rules state paths should be kept clear of foliage/garden waste</li> <li>Bar manager instructs staff on safe footwear</li> <li>Tennis coach advises members on safe footwear</li> <li>All areas of the club are inspected regularly</li> <li>Safe storage area for empty gas cylinders outside bar</li> <!--</td--><td><ul> <li>Continued monitoring of all areas of the club for obstructions and obstacles.</li> </ul></td><td>All club members</td><td>Ongoing Ongoing</td><td>ongoing Ongoing</td></ul>	<ul> <li>Continued monitoring of all areas of the club for obstructions and obstacles.</li> </ul>	All club members	Ongoing Ongoing	ongoing Ongoing	
	paths around the club is uneven and slippery when wet. Repave and where necessary widen all paths as a longer term solution. This may be done in stages. (low risk)	B) IVI	reviewed at M/C meetings	Oligoling	
	<ul> <li>External furniture etc. around clubhouse should be stored tidily. Broken furniture should be removed or repaired.</li> <li>(low risk)</li> </ul>	в/М	ongoing	Ongoing	
	Regular inspections of club facilities to ensure low H/S risks to all members and staff  Extra cleaning of Tudor Room after events			Ongoing	
	harmed and how?  ds (Medium /low Ri  Anyone using the club might trip and	Anyone using the club might trip and sustain an injury  • B/M inspects premises regularly & carries out repairs • There is a Maintenance Reporting book for recording faults. (located in the Kitchen) • There is an Accident Reporting book for recording accidents. (located in the kitchen) • A professional firm cleans the club. It has a schedule of work and reports to the B/M to identify problems • Floors are usually washed out-of-hours and are not wet when the club is in use. Wet floor sign available. • Adequate lighting throughout clubhouse and surrounds • Raised sills on the two doors to the exterior in the lounge are marked with hazard tape • Storage areas are provided and regularly reviewed • The allotment rules state paths should be kept clear of foliage/garden waste • Bar staff have been instructed to clean spillages promptly • Bar manager instructs staff on safe footwear • Tennis coach advises members on safe footwear • All areas of the club are inspected regularly • Safe storage area for empty gas cylinders outside	Anyone using the club might trip and sustain an injury  - B/M inspects premises regularly & carries out repairs  - There is a Maintenance Reporting book for recording accidents. (located in the Kitchen)  - There is an Accident Reporting book for recording accidents. (located in the kitchen)  - A professional firm cleans the club. It has a schedule of work and reports to the B/M to identify problems  - Floors are usually washed out-of-hours and are not wet when the club is in use. Wet floor sign available.  - Adequate lighting throughout clubhouse and surrounds  - Raised sills on the two doors to the exterior in the lounge are marked with hazard tape  - Storage areas are provided and regularly reviewed  - The allotment rules state paths should be kept clear of foliage/garden waste  - Bar staff have been instructed to clean spillages promptly  - Bar manager instructs staff on safe footwear  - All areas of the club are inspected regularly  - Safe storage area for empty gas cylinders outside  - Regular monitoring of lighting  - Continued monitoring of lighting  - Continued monitoring of lighting  - Continued monitoring of all areas of the club hereas of the club is uneven and slippery when wet.  Repave and where necessary widen all paths as a longer term solution. This may be done in stages. (low risk)  - External furniture etc. around clubhouse should be stored tidily. Broken furniture should be removed or repaired.  - (low risk)  - Regular inspections of club facilities to ensure low H/S risks to all members and staff  - Extra cleaning of Tudor Room after events	Anyone using the club might trip and sustain an injury	Anyone using the club might trip and sustain an injury

Hazard	Who might be harmed	Current control measures	Further actions required	Action by		Date
	and how?			whom	when	completed
2. Cutting Hazard	ls (Low Risk)					
<ul> <li>Broken glass</li> <li>Protruding nails</li> <li>Pieces of metal or wire</li> <li>Sharp edges</li> </ul>	<ul> <li>Anyone using the club could step on/brush against a sharp object and sustain an injury.</li> <li>The club has a bar and inevitably there are breakages: customers or staff could sustain cuts</li> <li>Karate members and Yoga participants exercise in bare feet and are particularly at risk</li> </ul>	<ul> <li>Cleaner scheduled to clean floor after functions where glass may be broken</li> <li>Karate members and Yoga participants lay down matting to exercise on</li> <li>Bar staff clear breakages promptly</li> <li>A container is provided in the bar for broken glass</li> <li>First aid boxes are located and clearly marked in entrance corridor and bar, and are kept up-to-date</li> </ul>		Club coach and Bar manager. B/M	ongoing	ongoing
3. Working at hei	ght (Low Risk)					
• Falls	Tradesman or B/M team working on roof, or using a step ladder inside or outside the clubhouse  Members putting up decorations	Ladders checked regularly     Step ladders kept in locked storeroom     Safety notices displayed by the ladders	Continued monitoring of ladder use.	H/S, B/M	ongoing	ongoing

Hazard	Who might be	Current control measures	Further actions required	Action by		Date
	harmed and how?			whom	when	completed
4. Hazardous subs	tances (Medium Risk)			•		
<ul> <li>Floor and surface cleaners</li> <li>Bar-pipe cleaners</li> <li>Cleaners used in glass washing m/c in bar</li> <li>CO<sub>2</sub> cylinders</li> <li>Garden fertilisers and chemicals such as weed killers</li> </ul>	<ul> <li>Cleaning or bar staff could damage skin /eyes by using materials incorrectly or as a result of a spillage or accident.</li> <li>Bar staff could be injured or asphyxiated if a CO<sub>2</sub> cylinder leaked or exploded</li> <li>Children playing at the club could swallow or come into contact with cleaners or garden chemicals and suffer poisoning/skin/ eye damage</li> </ul>	<ul> <li>Cleaning substances with flammable are kept in a locked container in storeroom</li> <li>Cleaners to use appropriate PPE</li> <li>Person buying cleaning materials buys only standard domestic products.</li> <li>CO<sub>2</sub> cylinders are chained in an upright position</li> <li>Staff are instructed in safe working practices with cylinders</li> <li>CO<sub>2</sub> safety notice is displayed adjacent to cylinders</li> <li>The allotment rules state that chemicals and fertilisers should be kept under lock and key.</li> <li>Safety notices in bar</li> </ul>	Check safety of cleaning materials in storeroom     Continued monitoring of compliance	H/S Officer		ongoing
5. Electrical faults	(High Risk)					
Faulty or damaged wiring, broken switches or faulty appliances	Electric shocks or burns to any club user	<ul> <li>Fixed installation inspected every 5 yrs by qualified electrician.</li> <li>All repairs done by qualified electrician</li> <li>Check list of portable electrical appliances</li> <li>Portable electrical appliances testing (PAT) every two years.</li> <li>Notices displayed stating location of main utility on/off switches</li> </ul>	<ol> <li>PAT testing of portable appliances in 2023</li> <li>New Fixed installation certificate issued Sept 2021 valid till 2026</li> </ol>	1. H/S Officer	March 2023	Dec 2023
Water penetration in office near light sockets			Leaking roof, roof repairs required	B/M	ASAP	Jan 2023

Hazard	Who might be harmed and how?	Current control measures	Further actions required	Action by		Date
		narmed and how?		whom	when	completed
6. Gas (Medium Ri	sk)					
Gas leaks  7. Heavy lifting (M	Any user of the club could suffer asphyxiation from a gas leak or injury from a gas explosion	<ul> <li>Gas installation and appliances inspected annually(in June) by Gas Safe registered engineer</li> <li>All repairs done by Gas Safe registered engineer</li> <li>All suspected leaks are promptly investigated.</li> </ul>	New gas meter fitted, gas instillation checked	H/S B/M		Nov 2023
				1	1	_
Moving barrels, crates, cylinders and other heavy items	Injury to bar staff when lifting	<ul> <li>Bar staff advised of appropriate clothing (e.g. footwear)</li> <li>Staff are instructed in safe lifting practice</li> <li>Staff are instructed to roll casks</li> <li>Records are kept of bar staff H&amp;S training</li> </ul>	Bar manager to continue all newly appointed staff	H/S Officer and Bar Manager		ongoing
8. Hygiene (High R	lisk)					
<ul> <li>Dirty tables, carpets etc</li> <li>Dirty toilets</li> <li>Poorly washed glasses</li> <li>Infestation by vermin or insects</li> <li>Animal faeces</li> <li>Lack of hand washing facilities</li> <li>Poor kitchen practices.</li> <li>Problem with mice</li> </ul>	Any user of the club could come into contact with harmful bacteria resulting in an infection or gastric upset     Children playing in the area in front of the club or in other parts of the grounds may step on or touch animal faeces possibly leading to infection	<ul> <li>A professional cleaner regularly cleans the club (including kitchen and toilets).</li> <li>A glass-washing m/c is used in the bar.</li> <li>Pest control measures are in place</li> <li>Food supplies (crisps, nuts etc) stored in plastic containers</li> <li>Disposable gloves/bags available for picking up animal faeces</li> <li>There are notices in the kitchen about safe food preparation</li> </ul>	Ongoing vigilance for pest infestation and action when/if appropriate	H/S, B/M		Ongoing

Who might be	Current control measures	Further actions required	Action by		Date
harmed and how?			whom	when	completed
s (Low Risk)			1	•	1
Anyone using the barbecue, or cooking food in the kitchen could come into contact with a hot surface or liquid and be burnt or scalded.	<ul> <li>Guidelines for use of the barbecue are displayed where the barbecue is stored</li> <li>Kitchen rules are displayed stating that children should not be in the kitchen while cooking is taking place.</li> <li>Frying is not allowed in the kitchen</li> <li>There are warning notices about hot water above the hand basins</li> </ul>	Continued checking that notices are in place Ongoing checking of compliance	H/S Officer		ongoing
g people and children.	(High Risk) and unaccompanied children		1	1	1
Members and visitors <18 years could be	Coaches who instruct children/young people are required to undergo DBS check	Check DBS records	Club Secretary	,	
subject to: • Physical and/or sexual abuse • Bullying (verbal, mental, physical)	There is a named person with responsibility for welfare and a poster gives contact details	Check information on responsible person is still current	Jane Cooper		
Young children and club members	Children under the age of 14 years should be supervised by a parent or guardian or qualified member of coaching staff at all times.	Management committee.			ongoing
	harmed and how?  s (Low Risk)  Anyone using the barbecue, or cooking food in the kitchen could come into contact with a hot surface or liquid and be burnt or scalded.  g people and children.  Members and visitors <18 years could be subject to:  • Physical and/or sexual abuse  • Bullying (verbal, mental, physical)  Young children and club	Anyone using the barbecue, or cooking food in the kitchen could come into contact with a hot surface or liquid and be burnt or scalded.  Members and visitors <18 years could be subject to:  Physical and/or sexual abuse  Bullying (verbal, mental, physical)  Poung children and club members  Pound in the kitchen while cooking is taking place.  Frying is not allowed in the kitchen  Frying is not allowed in the kitchen  There are warning notices about hot water above the hand basins  Coaches who instruct children/young people are required to undergo DBS check  There is a named person with responsibility for welfare and a poster gives contact details  Children under the age of 14 years should be supervised by a parent or guardian or qualified member of coaching	harmed and how?  s (Low Risk)  Anyone using the barbecue, or cooking food in the kitchen could come into contact with a hot surface or liquid and be burnt or scalded.  Members and visitors <18 years could be subject to:  Physical and/or sexual abuse  Bullying (verbal, mental, physical)  Page 16 Agus Agus Coulded in the wide and abuse embers  PGuidelines for use of the barbecue are displayed where the barbecue is stored  Continued checking that notices are in place Ongoing checking of compliance  Prying is not allowed in the kitchen There are warning notices about hot water above the hand basins  Check DBS records required to undergo DBS check There is a named person with responsibility for welfare and a poster gives contact details  Children under the age of 14 years should be supervised by a parent or guardian or qualified member of coaching  Management committee.	Nammed and how?   Whom   Whom   S (Low Risk)	Anyone using the barbecue, or cooking food in the kitchen could come into contact with a hot surface or liquid and be burnt or scalded.   Size are are awarning notices about hot water above the hand basins   Size are are displayed stating that children should not be in the kitchen while cooking is taking place.   Frying is not allowed in the kitchen

Hazard	Who might be harmed and how?		Further actions required	Action by		Date
				whom	when	completed
11. Fire (Medium	Risk)					
Fire caused by electrical fault, kitchen accident,	Anyone in the club house could suffer burns or asphyxiation if a fire	unnecessary storage of combustible material.  • Surplus exercise mats move to external storage area	Fire risk assessment to be updated annually	H/S Officer	ongoing	June 2023
vandalism, etc	new tractor yard.  The electrical installation is inspected every 5 years Portable electrical appliances are tested every 2 years The gas installation and boilers are inspected annually Fire routes and exits are signed and lit and kept clear There is an Emergency Assembly point, and fire drills are held regularly Fire-fighting equipment is in place and is tested annually Safety notice for use of the barbecue is displayed, and	Check fire action notices     and exit routes are     displayed and marked	H/S Officer	ongoing	ongoing	
		<ul><li>3. Remind Bar staff ensure fire exits are clear when they check premises at closing time.</li><li>4. Test fire alarms weekly</li></ul>	Bar manager	ongoing	Ongoing	
		<ul> <li>annually</li> <li>Safety notice for use of the barbecue is displayed, and a portable fire extinguisher provided</li> <li>Bar staff have been trained in use of fire-fighting equipment</li> <li>A phone is available during bar opening hours and staff have mobiles.</li> <li>Smoke detectors and fire alarms are installed throughout the clubhouse.</li> <li>The club was inspected by the Fire Brigade in January</li> </ul>	<ul><li>5. Replace all fire alarm units after 10 years</li><li>6. New fire inspection required in 2024</li></ul>	B/M	June 2028	Some fire alarms replaced in 2023

Hazard	Who might be	Who might be Current control measures	Further actions required	Action by		Date
	harmed and how?			whom	when	completed
12. Sports injuries	(High Risk)					
Accidents     Faulty equipment (Falls are covered elsewhere)	<ul> <li>Tennis players could be struck by a ball or racquet causing bruising or a more serious injury</li> <li>Karate members could sustain injury when performing combat moves</li> <li>Anyone playing sport or taking part in an activity at the club could damage muscles or tendons</li> </ul>	<ul> <li>Inexperienced tennis players are encouraged to have coaching.</li> <li>Coaches and instructors are fully qualified and provide programmes appropriate to the age and abilities of participants</li> <li>Medical supplies in first aid boxes are checked and kept up to date</li> <li>Coaches and instructors check and maintain all equipment and apparatus that is supplied by the club,</li> <li>Coaches and instructors advise members on the suitability of their equipment and clothing</li> </ul>	Advertise available in-house coaching	D/J H/S & B/M D/J D/J	Ongoing	Ongoing
• Slipping on Tennis Courts (high risk)	Poorly maintained tennis courts. Anyone slipping and falling on Tennis Courts (high Risk)	<ul> <li>Regular inspection of tennis courts.         Recommended a maintenance contract is taken out to ensure tennis court are safe to use in all conditions.</li> <li>Alternatively In-house system, where inspection are logged and remedial action taken.</li> <li>Courts are treated for moss twice yearly.</li> <li>Each court is brushed approx. monthly to</li> </ul>	Check clubs' accident insurance policy updated  Log book or Google Diary needs to be established to ensure that a regular maintenance programme is adhered too.	P/W P/W, H/H	Quarterly regular inspections required	Ongoing
Poorly maintained tractor	Hazard to drivers and club members	ensure even distribution of sand.  • Tractor regularly serviced	Courts 4/5/6 refurbished March 2021 Sand bins provided to allow adequate sand provision Aug 2021	P/W, H/H	Courts 4/5/6 being renewed 2024	Tractor serviced Sept 2021

Hazard	Who might be harmed and how?	Current control measures	Further actions required	Action by Whom	Date	Date Completed
13. Accidents, inju	l ries and illness (High Ri	isk)	<u> </u>			
Accidents, injuries and illness arising from medical conditions and not resulting from any of the above specific causes.	Any club member or visitor	<ul> <li>Some members are qualified in first aid (list displayed)</li> <li>Defibrillator available and some members have been instructed in its use</li> <li>Bar Manager has undergone first aid training.</li> </ul>	<ol> <li>Display list of those instructed in use of defibrillator</li> <li>Ensure all defibrillator components are in date.</li> </ol>	H/S B/M		New defibrillator installed Nov 2021
Not having sufficient numbers of first aiders	Club member fall ill or having a heart attack		Encourage member to have first aid training.	H/S		Training provided for members Nov 2023
Not reporting accidents Club location not recognised on Google maps	Remedial action might not be taken. Emergency services difficulty in locating club	<ul> <li>Make known in newsletter and display accident reporting book.</li> <li>Contact Google maps</li> </ul>	<ul><li>4. Item in news letter</li><li>5. Google maps have changed club location to Triangle Way.</li></ul>	H/S H/S		Aug 2021
14. Protection of n	ı nembers, visitors and p	ersonnel from unwanted visitors. Personal	। and public liability. (Medium Ris	k)		
Possible exposure of people on the premises to unwanted or unwarranted visitors,	Any club member or visitor on the premises	<ul> <li>All access gates to have a code entry system</li> <li>The clubhouse is normally closed and is accessible via swipe card.</li> <li>The bar area is locked by the bar personnel and alarmed.</li> </ul>	Close circuit faulty renewed 2023  Club card entry system replaced by keypad 2023	B/M H/S	Nov 2023	Feb 2023 March 2023
especially at night  Public and employee liability insurance is current.	Club or club member might be sued for	<ul> <li>Access to other function rooms is also given to limited and qualified persons.</li> <li>Check policies are current.</li> </ul>	Burglar alarm reviewed and updated  Management Committee			
Current.	neglect.		ivianagement committee			

15. Ris	sk to Building		
1)	Flat roof covering the lounge area.	Repairs are required on the flat roof covering the lounge area.	Ongoing
2)	Flat roof covering Tudor Room exit	Fla roof covering the tutor room exit needs to be replaced	
3)	Snooker Room	Snooker room ventilation needs to be improved	
4)	Damage to fire doors exit from Tudor Room	Repairs are required to the fire doors from the Tudor Room to Triangle Way.	